

**FIRE & INTRUSION ALARM RFP DEVICE LIST**

BUILDING INFORMATION								FIRE ALARM DEVICES																INTRUSION ALARM DEVICES									
Building #	Building Name	Address	City	Area (sf)	# Floors	8' Ladder or Lift for Ceiling Access	Region	OSY Tamper	Water Flow	Smoke Detector	Pull Station	PIV	Heat Detector	Duct Detector	Manual Tamper	Power Supplies	Remote Annunciators	Tamper Switches	Notification Devices	Batteries	Beam Detectors	Door Holders	Fire Hydrants	Dry Sprinkler Risers	Wet Sprinkler Risers	Electric Fire Pumps	Diesel Fire Pumps	Keypads	Door/Window Sensors	Motion Sensors	Batteries	Video Monitors	
11020	ACSO Training Academy	6289 Madigan Rd.	Dublin	16,808	1	Lift	East County	2	1	59	5	1	51				1		1	2					1								
11020	ACSO Training Academy - Gym, Hallway	6289 Madigan Rd.	Dublin	24,737	1	Ladder	East County	2	1	1	1	1		2	1				1	2					1								
11030	Animal Shelter	4595 Gleason Dr.	Dublin	15,569	1	Lift	East County		1		3		2	4					1	2					1			1	12	2	1		
11040	Office of Emergency Services (OES)	4985 Broder Blvd.	Dublin	14,200	1	Lift	East County	2	1	8	7	1		14	1		1		1	4					1								
11085	ACSO Firing Range/Class Room	5301 Madigan Rd.	Dublin	10,140	1	Lift	East County	2	1		3	2	7	5					1	2				2			3	6	2	2			
11100	Public Works Equipment Repair	6089 Madigan Rd.	Dublin	31,910	2	Lift	East County	2	1	10	8			3	1				1	2					1		2	28	0	1			
11110	Small Vehicle Repair/Fuel Station	6175 Madigan Rd.	Dublin	3,168	2	Lift	East County			4	4		24						1	2							1	12	1	1			
11115	BMD Warehouse	5390 Madigan Rd.	Dublin	15,000	1	Ladder	East County	2	1	1	1																						
11130	Public Works - Admin	4825 Gleason Dr.	Dublin	8,239	1	Lift	East County	2	1	18	1			3	1																		
14030	Household Hazardous Waste - East	5584 La Ribera St.	Livermore	5,240	1	Ladder	East County	2	1		6		11		1		1		1	2					1		1	9	4	1			
11050	California Highway Patrol	4999 Gleason Dr.	Dublin	11,915	1	Lift	East County			33	0	1	3		1																		